




Improvement through Innovation

Case Study: Improved Wear Liner Life




Wear is initiated at the bolt Hole location



Embedded Nuts on the Back side of the Wear liner Eliminates the surface hole where wear begins.



The operating surface Of the Wear Liner is clear of openings.



Side by Side test show Wear beginning at the On one side of the unit while the liners with Bolt holes show the Beginning of wear while The opposite side shows Very limited wear

